






| A  | B                         | C    |      | D   |
|----|---------------------------|------|------|-----|
| 1  | S205-047                  | 1646 | 350  | 2/6 |
| 2  | S205-048                  | 1650 | 252  | 3/6 |
| 3  | S205-170                  | 1728 | 260  | 2/6 |
| 4  | S205-171                  | 1188 | 260  | 2/6 |
| 5  | S205-172                  | 2000 | 250  | 1/6 |
| 6  | S205-173                  | 2000 | 250  | 1/6 |
| 7  | S205-174                  | 1600 | 260  | 2/6 |
| 8  | S205-707                  | 1650 | 503  | 3/6 |
| 9  | S205-511                  | 760  | 28   | 2/6 |
| 10 | S205-512                  | 851  | 1178 | 4/6 |
| 11 | S205-5584                 | 1397 | 100  | 3/6 |
| 12 | Основание с подъемн. мех. |      |      | 5/6 |
| 13 | n64                       |      |      | 6/6 |




|                                |                                |                               |                               |                               |                                   |                   |                                     |                                  |
|--------------------------------|--------------------------------|-------------------------------|-------------------------------|-------------------------------|-----------------------------------|-------------------|-------------------------------------|----------------------------------|
| 4x<br>φ6.3x20 mm<br><b>e17</b> | 54x<br>φ6.3x13 mm<br><b>e2</b> | 20x<br>φ8x30 mm<br><b>f1</b>  | 8x<br>M6<br><b>j10</b>        | 8x<br>φ6x35 mm<br><b>j115</b> | 4x<br>M6x84 mm<br><b>j117</b>     | 10x<br><b>k1</b>  | 8x<br>φ6xφ12/14 mm<br><b>o40</b>    | 4x<br>φ13x φ7/6 mm<br><b>o81</b> |
| 8x<br>φ3.5x16 mm<br><b>p38</b> | 24x<br>φ3x30 mm<br><b>p125</b> | 48x<br>φ4x35 mm<br><b>p26</b> | 4x<br>φ10x16 mm<br><b>r43</b> | 1x<br><b>z1</b>               | 12x<br>φ15x12 mm #16<br><b>r1</b> | 14x<br><b>r42</b> | 4x<br>115x115x122 mm<br><b>n106</b> |                                  |



# 2



# 3





# 7

Diagram 7 illustrates the assembly of the slatted bed base. The main drawing shows the bed frame with the headboard and the slatted base. A long cylindrical rod is shown being inserted into the headboard. Two callouts, 12.1 and 12.2, point to the slatted base. Callout 12.1 points to the hinge mechanism, and callout 12.2 points to the slats. An inset shows a close-up of the hinge mechanism.