









A	B	C	D
1	S171-005	365 x 94	1/1
2	S171-004-01	365 x 180	1/1
3	S171-132-01	468 x 480	1/1
4	S171-230	402 x 484	1/1
5	S171-229	402 x 484	1/1
6	S171-546	468 x 369	1/1
7	S171-570	400 x 82	1/1
8	S171-912	327 x 399	1/1
9	S171-133-01	468 x 480	1/1
10	S171-571	400 x 82	1/1
11	S171-520	312 x 82	1/1
12	S171-568	400 x 140	1/1
13	S171-569	400 x 140	1/1
14	S171-519	312 x 140	1/1







3



4



5



The diagram illustrates the assembly of the 1000 Series 2-Drawer Unit in five steps:

- I:** Shows the initial assembly of the drawer front (1) and side panels (7, 10, 11, 12, 13, 14) using screws e32. A callout shows the correct orientation of the screws.
- II:** Shows the drawer front (1) being attached to the side panels (7, 10, 11, 12, 13, 14) using screws e32.
- III:** Shows the drawer front (1) being attached to the side panels (7, 10, 11, 12, 13, 14) using screws e32. A callout shows the correct orientation of the screws.
- IV:** Shows the drawer front (1) being attached to the side panels (7, 10, 11, 12, 13, 14) using screws e32. A callout shows the correct orientation of the screws.
- V:** Shows the drawer front (1) being attached to the side panels (7, 10, 11, 12, 13, 14) using screws e32. A callout shows the correct orientation of the screws.

