




















Ipic/Ирис/Iris

Шафа 2Д
Шкаф 2Д
Wardrobe 2D




number	Measurements	Pcs.
1	1807x540	1
2	1807x540	1
3	890x562	1
4	890x562	1
5	100x856	1
6	856x537	1
7	1422x440	2
8	376x440	2
9	1437x436	2
10	389x875	1
11	582x238x77	1

12	582x238x77	1
15	555x	1
16	555x	1
17	961x	1
18	1419x	1
19	880x	1









1


I



x6



2



[illegible]



3

Diagram illustrating the assembly of the corner and side brackets (8) onto the frame (7) using screws (p1).


The diagram shows two corner brackets (8) being attached to the corners of the frame (7). The side brackets are also shown being attached to the side of the frame (7).

Labels: 8, x2, 7, x2, p1, a2.

4




5









4

6



7



5

8

